

ATTESTATION OF CONFORMITY CERTIFICATE

Certificate No: 20-IS-2631 -TAT-20-TPI-2271

Name and address of bearer / manufacturer: FAY MEKANİK MAKİNE SAN. ve TIC. LTD.

STI. Küçük Çamlıca Mah. Güler Sokak No1/B Üsküdar 34696 / İSTANBUL / TURKEY

Inspected according to: EN 12266-1 / EN 12516-3

Description of product: Selonoid Valve and Filters

Seri Numarası: SLFM and SLFM S Series (Selonoid Valve) / FFL Series (Filter)

Model & Type: DN15 / DN20 / DN25 (Selonoid Valve)
DN20 / DN25 (Filter)

Inspection date or period: 17.11.2020

Inspection Report No: 20-IS-2631 -TAT-20-0728-R2

Production Site: Küçük Çamlıca Mah. Güler Sokak No1/B - Üsküdar 34696 / İSTANBUL / TURKEY

Trade Mark: FAY

Inspected by: Demet AKTÜRK

We hereby certify that according to the results of the inspection, the product mentioned at this certificate fulfills the contractual requirements governing mission entrusted to TÜV Austria Türk. This Attestation of Conformity is issued on voluntary basis according to EN 12266-1 / EN 12516-3. It conforms that the listed equipment (not Annex IV equipment) complies with the principal protection requirements of the standard. It refers only to the particular sample and its technical documentation submitted for inspection.

İstanbul, Issue Date 17.11.2020

For and behalf of TÜV AUSTRIA TÜRK



20-IS-2631

FAY MEKANİK

INSPECTION REPORT

Inspection Requested By	FAY MEKANİK MAKINE SAN. ve TIC. LTD. STI. Küçük Çamlıca Mah. Güler Sokak No1/B Üsküdar 34696
Inspection Place	İSTANBUL
Inspection Dates	17.11.2020
Report No:	20-IS-2631-TAT-20-0728
Report Date:	17.11.2020
Issued by:	TÜV AUSTRIA TURK Belgelendirme Eğitim ve Gözetim Hizmetleri Ltd. Şti. Çamlık Mah. İkbal Cad. Dinç Sok. No:28/1 Ümraniye / İstanbul

Table of Contents

1	INSPECTION SUMMARY	3
2	SCOPE.....	3
3	DOCUMENT REVIEW	3
3.1	Drawings, ITP and Related Inspection Documents	3
3.2	Material and Component Certificates	3
4	SITE ACTIVITIES	3
4.1	Visual Inspection.....	3
4.2	Measurements	3
4.3	Tests & Witness	4
5	CONCLUSION.....	4
6	APPROVALS & DISCLAIMERS	4
7	PHOTOS.....	5

1 Inspection Summary

Third party supervision job to be given Filter Valves for the customer manufactured by Fay Mekanik Makine San. ve Tic. Ltd. Şti. according to EN 12266-1 / EN 12516-3.

2 Scope

Thirth party inspection

3 Document Review

3.1 Drawings, ITP and Related Inspection Documents

See Technical File; 20-IS-2631_AoCR1

3.2 Material and Component Certificates

See Technical File; 20-IS-2631_AoCR1

4 Site Activities

4.1 Visual Inspection

The product has been visually checked. There is no contrary to the order.
See Technical File; 20-IS-2631_AoCR1

4.2 Measurements

20-17189	Digital Caliper
20-38381	Manometer
20-17182	Manometer
20-39868	Thermometer
20-17187	Scales
20-18863	Air conditioning cabinet

4.3 Tests & Witness

Shell Strength Test
 Surface Leak Test
 Internal Leak Test
 Design Strength

See Technical File; 20-IS-2631_AoCR1

5 Conclusion

The third party audit was held on 17.11.2020 and it was determined that the products are suitable for EN 12266-1 and EN 12516-3 in the audit.

PRODUCT CODE	DIMENSION	CONNECTION TYPE	PRESSURE	PRODUCT NAME
FFL 20	3/4"	Gear	0-501 bar	Filter Valve
FFL 25	1"	Gear	0-501 bar	Filter Valve
FFL 20	3/4"	Gear	0-6 bar	Filter Valve
FFL 25	1"	Gear	0-6 bar	Filter Valve


6 Approvals & Disclaimers

The signatures below certify that this report has been reviewed and accepted and demonstrates that the signatories are aware of all the requirements contained herein and are committed to ensuring their provision.

This claim inspection report prepared on a best effort basis and is meant for information only. TÜV AUSTRIA TURK, with this report does not carry financial and legal obligation.

7 Photos

Attach photos as figures with the description;



	Name, Surname	Signature	Position	Date
Prepared by	Demet AKTÜRK		Technical Expert	17.11.2020
Approved by	Ali YAVRUOĞLU		Aegean Region Manager	17.11.2020

